

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- ✓ • TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1




FIG. 2

N9579, N9349, N9350, & N9351
SHEET 2 OF 37




FIG. 3




Fig. 4

N9579, N9349, N9350, + N9351
SHEET 4 OF 37




Fig. 5-




Figure 6

N9579, N9349, N9350 & N9351
SHEET 6 OF 37




Fig. 7

N9579, N4349, N4350 & N9351
SHEET 7 OF 37




Fig. 8

Digital Guitar Processor Circuit 112




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Figure 13




Fig. 11

N9579, N9349, N9350 ← N9351
SHEET 14 OF 37




Figure 15

Preamplifier Section




Figure 16

N9579, N9349, N9350 & N9351
SHEET 16 OF 37




Figure 17




Figure 18

N9579, N9349, N9350 + N9351
SHEET 18 OF 37







Fig. 19



N9579, N9349, N9350 & N9351
SHEET 20 OF 37





F16. 21c

N9579, N9349, N9350 & N9351
SHEET 22 OF 37




Figure 22 A




FIG. 22 B

N9579, N9349, N9350 + N9351
SHEET 24 OF 37




Figure 23

N9579, N9349, N9350 + N9351
SHEET 25 OF 37







Figure 24

224




Figure 25

N9579, N9349, N9350 & N9351
SHEET 27 OF 37




Figure 26




Figure 27

Passive Legacy system and Control Section










Figure 28

NOTE: All parts within this area powered by VPLL

Gibson Labs
1283 Old Mountain View Rd., Unit F
156
XY PrintopDocument Number
B
Date Friday, October 7, 2005


Sheet 1 of 4

F1: 24





Specified

Connector to be Specified




Pre Amplifiers


Summing Circuit



N9579, N9349, N9350 & N9351
SHEET 33 OF 37



N9579, N9349, N9350 + N9351
SHEET 34 OF 37



33




Fig. 34




Fig. 35

